


Exhibit "F"


Window Replacement Installation Details



Unacceptable Installation

NOT ALLOWED

Window installs over existing wood trim
Window extends beyond window trim



Acceptable Installation

ALLOWED

Window frame recessed from wood trim
Window frame flush with wood trim